


Amarillo Part III



Historic Resources Inventory Form—Route 66

County Potter City Amargillo Inventory # 375-AM-209

Historic Name _____

Current Name Vallet Cleaners

Address 4600 Bushland Co 9m & Bushland

Lot(s): _____ Block: _____ Addition: _____

Owners Address _____

Resource type Building Structure Site Object District

Landscape/Site Features _____

Outbuildings _____

Function: Current Use service Historic Use restaurant?

Construction Date: 1960 Actual Estimated

Architect _____ Builder _____

Possible Threat(s) Demolition Development Neglect Alteration Vacant Utility Expansion

Integrity Location Design Materials Workmanship Setting Feeling Association

USGS Quad #: _____ Year: _____ UTM Zone: _____ Easting: _____ Northing: _____

Priority High Medium Low Recorder Monica Penick Date(s) 7/18/2002



Stylistic Influence(s) _____

Roof type front gable (xassy. roof) Materials corr. shingle

Wall facade front: horiz wood siding rear: brick Foundation _____

Window type plate in metal w/ wood surround Materials vertical grooved metal siding

Door type fully glazed in metal w/ lg side Materials as siding

Porch type overhanging gable-type roof Materials _____

Number of Stories 1 1/2 Plan _____

Chimney(s) _____

General Architectural Description horiz wood siding in gable end

drive-up windows on S & E elev.

Photo Data: Roll 30 Frame _____ Feature 16 Look NW

APR 21 10 2001

020

34266

375-AM-209
30-3766-18
FACING NW

Historic Resources Inventory Form—Route 66

County POTTER City AMARILLO Inventory # 375-AM-210

Historic Name _____

Current Name Kelley Roofing

Address 4615 Ashland

Lot(s): _____ Block: _____ Addition: _____

Owners Address _____

Resource type Building Structure Site Object District

Landscape/Site Features _____

Outbuildings _____

Function: Current Use Commercial Historic Use Commercial / AUTO SERVICE

Construction Date: 1947 (w/ additions) Actual Estimated

Architect _____ Builder _____

Possible Threat(s) Demolition Development Neglect Alteration Vacant Utility Expansion

Integrity Location Design Materials Workmanship Setting Feeling Association

USGS Quad #: _____ Year: _____ UTM Zone: _____ Easting: _____ Northing: _____

Priority High Medium Low Recorder Monica Penick Date(s) 7/18/2002



Stylistic Influence(s) _____

Roof type _____ Materials _____

Wall facade _____ Foundation _____

Window type _____ Materials _____

Door type _____ Materials _____

Porch type _____ Materials _____

Number of Stories _____ Plan 

Chimney(s) _____

General Architectural Description 1 part commercial block; 2 separate bldgs

Ⓚ flat roof, red brick; plate in metal; 2 w's - both set in heavy wood framed - framed, glazed in wood w/ transom

Ⓛ flat, red brick; divided plate in metal w/ wood surround; 1 overhead bay w/ one multi-panel overhead door; main door ported has overhead-type door inserted

Photo Data: Roll 30 Frame _____ Feature 20 (B) south end 101-116

19 (A) N end 100-SE



Historic Resources Inventory Form—Route 66

County Pope City Amerville Inventory # 375 - AM - 211
Historic Name _____
Current Name Clutches Plus
Address @ int of Bushland, Hillcrest S 9th
Lot(s): _____ Block: _____ Addition: _____
Owners Address _____
Resource type Building Structure Site Object District
Landscape/Site Features _____
Outbuildings _____
Function: Current Use VACANT Historic Use AUTO
Construction Date: 1950 Actual Estimated
Architect _____ Builder _____
Possible Threat(s) Demolition Development Neglect Alteration Vacant Utility Expansion
Integrity Location Design Materials Workmanship Setting Feeling Association
USGS Quad #: _____ Year: _____ UTM Zone: _____ Easting: _____ Northing: _____
Priority High Medium Low Recorder Monica Penick Date(s) 7/11/2002



Stylistic Influence(s) _____

Roof type flat w/ mansard style (shingled) Materials COANIC

Wall facade COANIC brick Foundation _____

Window type _____ Materials _____

Door type 1 wood door, ADA orig 6 panel metal Materials 3 over head bays w/ ADA orig metal doors

Porch type overhanging concrete on wood posts Materials _____

Number of Stories _____ Plan _____

Chimney(s) _____

General Architectural Description _____

Photo Data: Roll 30 Frame _____ Feature 17 look S

001 01 000000 0000 0000

001

94267

375-AM-211
30-3766-17
FACING SOUTH

Historic Resources Inventory Form—Route 66

County POTTER City AMARILLO Inventory # 375-AM-212

Historic Name _____

Current Name COUNTRY CLUB ANTIQUES

Address 4503 Bushland

Lot(s): _____ Block: _____ Addition: _____

Owners Address _____

Resource type Building Structure Site Object District

Landscape/Site Features outlines of foundation visible

Outbuildings barn-type storage shed, not permanent & not old

Function: Current Use retail Historic Use garage/gas

Construction Date: 1940 Actual Estimated

Architect _____ Builder _____

Possible Threat(s) Demolition Development Neglect Alteration Vacant Utility Expansion

Integrity Location Design Materials Workmanship Setting Feeling Association

USGS Quad #: _____ Year: _____ UTM Zone: _____ Easting: _____ Northing: _____

Priority High Medium Low Recorder Monica Penick Date(s) 7/18/2002



Stylistic Influence(s) _____

Roof type flat w/ parapet & conc cop Materials _____

Wall facade red brick Foundation _____

Window type 3 part plate in wood w/ transoms Materials _____

Door type 2 overhead bays, multipanel wood door; main door = framed glazed in wood w/ transom Materials _____

Porch type _____ Materials _____

Number of Stories 1 Plan _____

Chimney(s) _____

General Architectural Description transoms in rear on SW etc - solid doors in wood frame w/ transom

Photo Data: Roll 30 Frame _____ Feature 15 1047 SW

PHOTOGRAPH UNIT - 1 (ECL)

012

94258

375-AM-212
30-3766-16
FACING SW

Historic Resources Inventory Form—Route 66

County Potter City Amargosa Inventory # 575-AM 213 12
Historic Name _____
Current Name Bel Air Appo
Address 701 W. 7th / (overhead)
Lot(s): _____ Block: _____ Addition: _____
Owners Address _____
Resource type Building Structure Site Object District
Landscape/Site Features _____
Outbuildings _____
Function: Current Use residential Historic Use motels ?
Construction Date: 1960 Actual Estimated
Architect _____ Builder _____
Possible Threat(s) Demolition Development Neglect Alteration Vacant Utility Expansion
Integrity Location Design Materials Workmanship Setting Feeling Association
USGS Quad #: _____ Year: _____ UTM Zone: _____ Easting: _____ Northing: _____
Priority High Medium Low Recorder Monica Penick Date(s) 7/10/02



Stylistic Influence(s) _____

Roof type ① side gable ② side gable

Materials congr shingle

Wall facade ① red brick ② red brick

Foundation _____

Window type ① vinyl ② metal sash (1/1)

Materials _____

Door type ① obscured ② solid

Materials _____

Porch type ① front gable
low 2nd story porch

② followed by off

Materials congr 7 2nd story walkway

Number of Stories ① 1 ② 2

Plan _____

supported on dec post piers

Chimney(s) _____

L of off is

General Architectural Description 12 units office is sm house
or 14

Photo Data: Roll 30 Frame _____ Feature 15 overall 5 units front E

14 other face NW

